| | | |
|---|---|---|
| Applies to | : | Tubes SRO 09/50 and SRO 09/51 with Optimus generators |
| Short Description | : | SRO 09/50 tubes **must not** be used for Optimus RAD+/RF+C generators. |
| Symptom | : | The **SRO 09/50 tube (9874 007 01122)** has a resistor in line with the small focus.<br>Optimus generators set a standby filament current which is much higher compared to predecessor generators. This leads to overheating of the oil and the tube housing. |
| Solution | : | The resistor in line with the small focus is not required in combination with an Optimus generator, therefore the tube type<br>**SRO 09/51 (9890 00 63181)**<br>is available which does not have this resistor.<br><br>**Only this tube type must be used in combination with an Optimus.**<br><br>SRO 09/50 does not exist in the compatibility list of Optimus generators since 1997. |